



OPEL ASTRA SPORTS TOURER: 1LTL303

Vinnumber:	WOLPE8E63G8028283	Versionname:	1.6 CDTI 81kW ecoFLEX S/S Ultim. Pl. Ed
First Registrationdate:	1/12/2015	Fiscalpower:	
Expertise Mileage:	66916	Power Kw:	81
Bodytype:		Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3504
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining semi-artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/50/17/92 MS LightMetal			
Winter tyres:	Fr.L.	Pirelli: 4 mm	Fr.R.	Pirelli: 4 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	1139,68
Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80





Roof, Chemical pollution, LI - Repair and paint (complete) 481,50



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Repaired, Acceptable 0,00

No pictures to display

Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Headlight R, Scratch(es), 67 - Polish 0,00



Wing F R, Scratch(es), LI - Repair and paint (complete) 220,18



Rearview mirror basis L, Scratch(es), Smart repair 110,64



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete) 115,56



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display