


VOLKSWAGEN Transporter: 1JEY804

Vinnumber:	WV1ZZZ7HZFH069455	Versionname:	TRANSP.1200 B/F SWB 84PK
First Registrationdate:	28/11/2014	Fiscalpower:	
Expertise Mileage:	151199	Power Kw:	62
Bodytype:		Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3322
Number of doors:	6		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Type of Tow bar	No Tow bar
Windows electric F			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	No GPS		
Type of Lining	Lining artificial leather		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/65/16/105 T Steel				
Summer tyres:	Fr.L.	Uniroyal: 4 mm	Fr.R.	Uniroyal: 4 mm
	Re.L.	Uniroyal: 4 mm	Re.R.	Uniroyal: 4 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	409,71
Bumper R, Scratch(es), Acceptable	0,00
No pictures to display	
Maintenance book, Missing, E - Replace	0,00
No pictures to display	
Bodywork, Not original part, Acceptable	0,00
No pictures to display	
Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	231,15



Bumper F, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F L, Dent(s), PDR - Paintless dent repair	63,00



Rearview mirror housing R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Trunk door R L, Dent(s) and scratch(es), It - Spot repair	115,56

