



VOLKSWAGEN GOLF VII: 1LET142

Vinnumber:	VWVZZZAUZGW093011	Versionname:	1.6 TDI TRENDLINE
First Registrationdate:	8/09/2015	Fiscalpower:	
Expertise Mileage:	67262	Power Kw:	81
Bodytype:		Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3811
Maintenance:	IN 15600 KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage	SD	Luggage cover
GPS storage		Front parking sensors
Windows electric F		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

195/65/15/91 V Steel				
Summer tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	1947,20
Wheel cover F L, Scratch(es), E - Replace	30,00



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

0,00



Seat cover R, Stain, Cleaning

25,00



Sill outer L, Dent(s) and scratch(es), LI - Repair and paint (complete)

406,50



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

500,20



Trunk lid covering R, Scratch(es), Acceptable

0,00

No pictures to display

Wheel cover F R, Scratch(es), E - Replace

30,00



Rearview mirror housing R, Missing, Le - Replace and paint

170,96



Ceiling, Stain, Cleaning

50,00



Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

244,18



Mirror side blinker R, Broken, E - Replace

30,00



Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete)

0,00



Wheel cover R R, Scratch(es), E - Replace

30,00



Wing R L, Dent(s), Acceptable

0,00

No pictures to display

Interior, Not original part, Acceptable

0,00



Seat cover F L, Stain, Acceptable

0,00

No pictures to display

Seat cover F R, Stain, Cleaning

25,00



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

259,80



Mirror side blinker L, Crack, E - Replace

30,00



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)

115,56



Bumper F, Scratch(es), Acceptable

0,00

No pictures to display