



## VOLKSWAGEN PASSAT VARIANT: 1LSF089

Vinnumber:	WVWZZZ3CZGE113638	Versionname:	2.0 TDI MSQ VARIANT HIGHLINE
First Registrationdate:	20/11/2015	Fiscalpower:	
Expertise Mileage:	168865	Power Kw:	110
Bodytype:		Body color:	White
Gearbox:	Automatic	Paint type:	Opaque
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1733
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

## Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar removable
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

## Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	NOT OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

## Degree of wear

<b>215/55/17/94 Y LightMetal</b>				
Summer tyres:	Fr.L.	Vredestein: 3 mm	Fr.R.	Vredestein: 3 mm
	Re.L.	Vredestein: 3 mm	Re.R.	Vredestein: 3 mm

## Assistance equipment

Repair kit	No	Compressor	No
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1397,62
-------------------	---------

Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Tyre repair kit, Missing, E - Replace	210,53
---------------------------------------	--------



Rocker panel inner R L, Dent(s), LI - Repair and paint (complete) 115,56



Door R L, Dent(s), LI - Repair and paint (complete) 318,35



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Dent(s), LI - Repair and paint (complete) 220,18



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Wing moulding F L, Unclasp(ed), N - Mount/Dismount 14,40



Bonnet, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00

