



VOLKSWAGEN Caddy: 1JEB229

Vinnumber:	WV2ZZZ2KZFX058218	Versionname:	CADDY MAXI LIFE Trendl.102PK OMBOUW Dub.
First Registrationdate:	21/11/2014	Fiscalpower:	
Expertise Mileage:	151479	Power Kw:	75
Bodytype:		Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2433
Maintenance:	OVER 14700 KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Central consol F
Cruise Control	Rear parking sensors
Radio multimedia	Type of Tow bar
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Manual climate control
	Tow bar fixed

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/94 H Steel			
Winter tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Uniroyal: 6 mm	Re.R.	Uniroyal: 6 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	693,62
Wheel cover F L, Scratch(es), E - Replace	22,50



Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete)

362,02



Sliding door L, Repaired, P - Check

0,00



Supplementary brake lights, Broken, E - Replace

33,00



Ceiling, Dirty, Cleaning

25,00



Wheel cover R L, Broken, E - Replace

22,50



Wheel cover F R, Scratch(es), E - Replace

22,50



Trunk lid covering R, Broken, E - Replace

74,00



Protection plate M, Tear, E - Replace

109,60



Wheel cover R R, Scratch(es), E - Replace

22,50

