



VOLVO XC70: 1KJG647

Vinnumber:	YV1BZ73C1G1235262	Versionname:	2.0 D4 133KW MOMENTUM
First Registrationdate:	11/05/2015	Fiscalpower:	
Expertise Mileage:	187873	Power Kw:	133
Bodytype:		Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4228
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	Tow bar removable
Seats F heated			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	235/55/17/92 MS LightMetal			
Winter tyres:	Fr.L.	Pirelli: 4 mm	Fr.R.	Pirelli: 4 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			255,36
Bumper F M, Scratch(es), It - Spot repair			110,64




Windscreen, Stone chip(s), Windscreen repair 0,00



Wing R R, Dent(s), Acceptable 0,00

No pictures to display

Bonnet, Hail damage, PDR - Hail 0,00



Bumper grille, Broken, E - Replace 34,08



Bumper trim R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F M, Deformed / Strained, Smart repair 110,64

