



VOLVO V90: 1RLU998

| | | | |
|------------------------------------|--------------------------|--------------|-----------------------------------|
| Vinnumber: | YV1PWA8BDH1013571 | Versionname: | 2.0 D4 GEARTRONIC MOMENTUM |
| First Registrationdate: | 24/01/2017 | Fiscalpower: | |
| Expertise Mileage: | 123278 | Power Kw: | 140 |
| Bodytype: | | Body color: | Dark Blue |
| Gearbox: | Automatic | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 2612 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|-----------------------|
| Windows electric F | Sun Roof electric |
| Windows electric R | Panoramic roof |
| Cruise Control | Central consol F |
| Steering wheel multifunctional | Luggage cover |
| Radio multimedia | Front parking sensors |
| Type of headlighting | Rear parking sensors |
| Type of GPS | Type of Tow bar |
| Type of Lining | |
| Type of climate control | |

Headlighting LED
GPS big screen color
Lining leather
Autom climate control
No Tow bar

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|-----------------------------------|-------|---------------------|-------|---------------------|
| 225/55/17/101 W LightMetal | | | | |
| Summer tyres: | Fr.L. | Kleber: 4 mm | Fr.R. | Kleber: 4 mm |
| | Re.L. | Kleber: 4 mm | Re.R. | Kleber: 4 mm |

Assistance equipment

| | |
|--|----------|
| Number of charging cables (normal) | 0 |
| Number of charging cables (rapid charge) | 0 |

| | |
|--|-------------|
| Total cost ex VAT | 0,00 |
| Bumper R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Windscreen, Stone chip(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Door F R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Door F L, Scratch(es), Acceptable | 0,00 |

No pictures to display