







DS 4: 1NBY198







Vinnumber:	VF7NXBHXMFY579380
First Registrationdate:	15/01/2016
Expertise Mileage:	62581
Bodytype:	Hatchback

 Gearbox:
 MAN 6 VIT

 Transmission:
 Front

 Fueltype:
 Diesel

 Maintenance
 OK

 Maintenance
 OVER 18400 KM

 Battery functioning
 Yes

 Number of doors
 5

 Number of seats
 5

 Number head rests
 5

 Rims summer
 Aluminium

Category Passenger Car
Oil level OK
Registration Certificate Car (BE) Yes

Versionname: 1.6 BLUEHDI 115 BUSINESS GPS

Fiscalpower:

Power Kw:
Body color
Paint type
Rims summer
Oil level
Parking lot

Metalic Aluminium OK 3813

85

Grey

Options

Radio CD Central consol F
Windows electric F
Windows electric R
Cruise Control Rear parking sensors
Steering wheel multifunctional Type of Tow bar

Radio multimedia
Type of headlighting Headligh
Type of GPS GPS big

Type of Lining
Type of climate control
Sport seats

Headlighting Halogen GPS big screen color Lining fabrics Autom climate control No Tow bar

**Limited Technical Inspection** 

Airco functioning ок Battery functioning Yes Tires wear profile Power steering ок Yes Idle position Sound engine OK OK Engine startingtime oĸ Clutch test ок Exhaust gass Wiper fluid level OK OK Handbrake Transmission ок OK Lighting oĸ Wiperblades ок

Degree of wear

| 215/55/17/98 V LightMetal | Fr.L. | Uniroyal: 7 mm | Fr.R. | Uniroyal: 7 mm | Re.L. | Uniroyal: 8 mm | Re.R. | Uniroyal: 8 mm |

Assistance equipment

Emergency spare wheel Yes Jack Yes

Total cost ex VAT

Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)

115,56





Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)

95,00





