



AUDI A4 AVANT: 1JSJ555

Vinnumber:	WAUZZZ8K6FA094716	Versionname:	2.0 TDI ULTRA 100KW
First Registrationdate:	13/02/2015	Fiscalpower:	
Expertise Mileage:	131109	Power Kw:	100
Bodytype:	Break	Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1507
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Sun Roof electric
Windows electric F	Panoramic roof
Windows electric R	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Front parking sensors
Seats F heated	Rear parking sensors
Radio multimedia	Type of Tow bar
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control
	No Tow bar

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/92 V LightMetal				
Summer tyres:	Fr.L.	BF Goodrich: 4 mm	Fr.R.	BF Goodrich: 4 mm
	Re.L.	BF Goodrich: 4 mm	Re.R.	BF Goodrich: 4 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1550,82
Wing R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Windscreen, Crack, E - Replace	0,00



Protection plate M, Deformed / Strained, E - Replace 74,00



Wing F R, Dent(s) and scratch(es), Le - Replace and paint 530,02



Bonnet, Dent(s) and scratch(es), LI - Repair and paint (complete) 0,00



Headlight R, Broken, E - Replace 0,00



Door R R, Repaired, Acceptable 0,00

No pictures to display

Bumper F, Dent(s) and scratch(es), Le - Replace and paint 735,00



Bumper grille F R, Missing, E - Replace 0,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80

