



AUDI A5 SPORTBACK: 1LNB517

Vinnumber:	WAUZZZ8T7GA011434	Versionname:	2.0 TDI ULTRA 100KW
First Registrationdate:	26/10/2015	Fiscalpower:	
Expertise Mileage:	100360	Power Kw:	100
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	19600	Parking lot:	2614
Maintenance:	OK		
Maintenance:	631 DAGEN		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	4		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection



Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/50/17/94 H LightMetal				
Winter tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			115,56
Door R L, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Door F L, Dent(s) and scratch(es), Acceptable			0,00

<i>No pictures to display</i>		
Wing R L, Repaired, Acceptable		0,00
<i>No pictures to display</i>		
Windscreen, Stone chip(s), Acceptable		0,00
<i>No pictures to display</i>		
Rear bulkhead lining, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Bumper F, Scratch(es), It - Spot repair		115,56
		
Outer backrest protection L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Bumper R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Door R R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Sill outer R, Dent(s) and scratch(es), Le - Replace and paint		0,00
		
Door R L, Repaired, P - Check		0,00
<i>No pictures to display</i>		
Tires, Not original part, Acceptable		0,00
<i>No pictures to display</i>		
Bumper R, Repaired, Acceptable		0,00
<i>No pictures to display</i>		