



BMW 1 HATCH: 1UMD975

Vinnumber:	WBA1V910405G94123	Versionname:	1.5 116D EFFICIENTDYNAMICS EDIT. (85KW)
First Registrationdate:	13/01/2017	Fiscalpower:	
Expertise Mileage:	44998	Power Kw:	85
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance	1/12/2019	Parking lot:	4213
Maintenance	NOT OK		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F
GPS storage	HD	Luggage cover
GPS storage		Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------








Total cost ex VAT		1003,30
-------------------	--	---------

Alloy rim R L, Scratch(es), Acceptable		0,00
--	--	------

No pictures to display

Door R R, Dent(s), Acceptable		0,00
-------------------------------	--	------

No pictures to display

Door F R, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
	
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
	
Maintenance, Maintenance, Execute	0,00
	
Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80
	
Roof, Chemical pollution, LI - Repair and paint (complete)	481,50
	
Seat cover F R, Stain, Cleaning	25,00
	
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
	
Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bonnet, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	