



AUDI A1 SPORTBACK: 1PUP675

Vinnumber:	WAUZZZ8X1HB028521	Versionname:	1.4 TDI 66kW
First Registrationdate:	22/09/2016	Fiscalpower:	
Expertise Mileage:	90619	Power Kw:	66
Bodytype:		Body color:	Silver
Gearbox:	MAN 5 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2230
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Luggage cover
Windows electric F	Rear parking sensors
Windows electric R	Type of Tow bar
Steering wheel multifunctional	No Tow bar
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK


Degree of wear

	185/60/15/88 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	936,96
Door F L, Dent(s), LI - Repair and paint (complete)	254,68



Sill outer R, Dent(s), LI - Repair and paint (complete)

248,40



Alloy rim F L, Scratch(es), Acceptable

0,00

No pictures to display


Bumper F, Scratch(es), LI - Repair and paint (complete)

169,44



Bumper R, Scratch(es), LI - Repair and paint (complete)

169,44



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00

