



VOLVO XC90: YJ4302

Vinnumber:	YV1LF68UCK1468405	Versionname:	2.0 D5 4WD Geartronic Inscription 7PL
First Registrationdate:	28/02/2019	Fiscalpower:	
Expertise Mileage:	12903	Power Kw:	173
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2605
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	No		

Options

GPS storage	HD	Seats electric F L
GPS storage		Seats electric F R
Windows electric F		Central consol F
Windows electric R		Luggage cover
Cruise Control		Front parking sensors
Steering wheel multifunctional		Rear parking sensors
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting LED	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	NOT OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	275/45/20/110 V LightMetal			
Winter tyres:	Fr.L.	Vredestein: 5 mm	Fr.R.	Vredestein: 5 mm
	Re.L.	Vredestein: 5 mm	Re.R.	Vredestein: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1129,18
Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)	95,00



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

382,02



Bumper R, Scratch(es), LI - Repair and paint (complete)

254,16



Wing moulding F R, Scratch(es), Le - Replace and paint

120,00



Door R L, Scratch(es), Acceptable

0,00



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Door F R, Dent(s), PDR - Paintless dent repair

63,00



Wing trim R R, Scratch(es), Le - Replace and paint

120,00

