



VOLVO V60: 1HUJ504

Vinnumber:	VV1FW8481F1238746	Versionname:	V60 BRE D2 Kinetic 115PK
First Registrationdate:	6/10/2014	Fiscalpower:	
Expertise Mileage:	87308	Power Kw:	84
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	3729
Maintenance:	SERVICE 0KM 0D		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	HD Rear parking sensors
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining semi-artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/96 H LightMetal			
Winter tyres:	Fr.L.	Semperit: 3 mm	Fr.R.	Semperit: 3 mm
	Re.L.	Semperit: 7 mm	Re.R.	Semperit: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT 1985,68

Door F R, Scratch(es), LI - Repair and paint (complete) 318,35



Tailgate, Repaired, Acceptable 0,00

No pictures to display

Door F L, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Wing F R, Scratch(es), LI - Repair and paint (complete) 220,18



Seat cover F R, Dirty, Cleaning 25,00



Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80




Door frame F R, Scratch(es), Acceptable 0,00

No pictures to display

Maintenance, Maintenance, Execute 0,00



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Door R L, Dent(s), Acceptable 0,00

No pictures to display

Wing R L, Dent(s), Acceptable 0,00

No pictures to display

Bonnet, Chemical polution, Acceptable 0,00

No pictures to display

Seat cover F L, Dirty, Cleaning 25,00



Floor covering F L, Hole, E - Replace 252,00



Wing R R, Scratch(es), LI - Repair and paint (complete) 308,20

