



VOLKSWAGEN Touran: 1JGP766

Vinnnummer:	WVGZZZ1TZFW038571	Versionname:	TOURAN Highline 7pl. 105PK
First Registrationdate:	12/12/2014	Fiscalpower:	
Expertise Mileage:	65565	Power Kw:	77
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3227
Maintenance:	OVER 14400 KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Radio multimedia	No Tow bar
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Sport seats	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Winter tyres:	205/55/16/91 H LightMetal			
	Fr.L.	Other: 7 mm	Fr.R.	Other: 7 mm
	Re.L.	Goodyear: 7 mm	Re.R.	Goodyear: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	778,08
-------------------	---------------

Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80
---	---------------



Interior, Dirty, Chemical cleaning 100,00



Door R R, Scratch(es), Acceptable 0,00



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Boot carpet, Dirty, Chemical cleaning 100,00



Alloy rim R R polished, Scratch(es), Acceptable 0,00



Door trim F R, Scratch(es), Smart repair 110,64



Bumper grille F R, Scratch(es), Smart repair 110,64



Door F L, Scratch(es), 67 - Polish 50,00

