



BMW 3 GRAN TURISMO: 1LFB556

Vinnumber:	WBA8Y510X0G430386	Versionname:	2.0 318D (100KW) GRAN TURISMO
First Registrationdate:	10/09/2015	Fiscalpower:	
Expertise Mileage:	62220	Power Kw:	100
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2607
Maintenance:	SERVICE IN 1400KM 9 2020		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Sun Roof electric	
GPS storage	HD	Panoramic roof	
GPS storage		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/55/17/97 H LightMetal				
Winter tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			478,36
Seat cover F R, Stain, Cleaning			25,00



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Dent(s), Acceptable 0,00

No pictures to display

Sill trim R, Scratch(es), It - Spot repair 115,56



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Dent(s), PDR - Paintless dent repair 63,00



Door R L, Dent(s), PDR - Paintless dent repair 63,00

