



BMW 5 BERLINE: 1KJU877

Vinnumber:	WBA5E31030G040164	Versionname:	2.0 518D (100KW)
First Registrationdate:	18/05/2015	Fiscalpower:	
Expertise Mileage:	163093	Power Kw:	100
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4221
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage	HD	Front parking sensors
GPS storage		Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining artificial leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	NOT OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/55/17/97 V LightMetal				
Summer tyres:	Fr.L.	Continental: 3 mm	Fr.R.	Continental: 3 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	494,72
Wing R L, Repaired, P - Check	0,00



Wing F L, Scratch(es), It - Spot repair

115,56



Rear window, Not original part, Remove lettering

25,00



Dashboard, Scratch(es), Acceptable

0,00



Bumper R, Repaired, P - Check

0,00



Door R L, Repaired, P - Check

0,00



Alloy rim F R, Scratch(es), I - Repair

100,00



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

254,16

