



BMW 5 TOURING: 1RLC802

Vinnumber:	WBA5L31080G124776	Versionname:	520d (120 kW)
First Registrationdate:	18/01/2017	Fiscalpower:	
Expertise Mileage:	73223	Power Kw:	120
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	3230
Maintenance:	SERVICE -7000KM 1 2020		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L
GPS storage	HD	Seats electric F R
GPS storage		Sun Roof electric
Windows electric F		Panoramic roof
Windows electric R		Central consol F
Cruise Control		Luggage cover
Steering wheel multifunctional		Front parking sensors
Seats F heated		Rear parking sensors
Radio multimedia		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	
Head-up Display		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/55/17/97 H LightMetal				
Winter tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			2112,07
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)			95,00



Wing R R, Dent(s), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Dent(s), Acceptable 0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete) 254,16



Windscreen, Stone chip(s), Windscreen repair 58,80



Maintenance, Maintenance, Execute 0,00



Bonnet, Dent(s), LI - Repair and paint (complete) 396,09



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Roof, Dent(s), Acceptable 0,00

No pictures to display

Wing F L, Dent(s) and scratch(es), Le - Replace and paint 612,02





Xenon headlight L, Scratch(es), E - Replace

696,00

