



BMW X5: 1KRA170

Vinnumber:	WBAKS210200N37768	Versionname:	X5 xDrive 25d
First Registrationdate:	12/06/2015	Fiscalpower:	
Expertise Mileage:	140753	Power Kw:	155
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	4 Weel	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	SERVICE IN 1500KM 2 2021	Parking lot:	2633
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L
GPS storage		Seats electric F R
GPS storage	HD	Sun Roof electric
Windows electric F		Panoramic roof
Windows electric R		Central consol F
Cruise Control		Luggage cover
Steering wheel multifunctional		Front parking sensors
Seats F heated		Rear parking sensors
Radio multimedia		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	
Head-up Display		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

255/50/19/107 V LightMetal				
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

	Runflat	Yes
--	---------	------------

Total cost ex VAT	1803,96
-------------------	----------------

Bumper F, Scratch(es), LI - Repair and paint (complete)	254,16
---	---------------



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Door R R, Dent(s), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 254,16



Floor covering F L, Worn, Acceptable 0,00

No pictures to display

Ignition key, Missing, E - Replace 150,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper spoiler F, Scratch(es), E - Replace 48,00



Door R L, Dent(s), Acceptable 0,00

No pictures to display

Outer valance R, Scratch(es), Acceptable 0,00

No pictures to display

Foglight L, Broken, E - Replace 156,00



Wing R R, Dent(s), Acceptable 0,00

No pictures to display

Windscreen, Stone chip(s), E - Replace 560,64



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Wing trim R R, Scratch(es), E - Replace

96,00



Door F L, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display