


MERCEDES A: 1HZR610

Vinnumber:	WDD1760111V039856	Versionname:	A 160 CDI 90PK
First Registrationdate:	7/11/2014	Fiscalpower:	
Expertise Mileage:	94264	Power Kw:	66
Bodytype:		Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1528
Number of doors:	5		
Number of seats:	5		
Number head rests:	1		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	HD	
Windows electric F		
Windows electric R		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining semi-leather	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/40/18/92 H LightMetal			
Winter tyres:	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	756,44
Door seal F L, Deformed / Strained, E - Replace	54,00



Seat cover F L, Worn, Acceptable

0,00



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

211,80



Bumper F, Scratch(es), Acceptable

0,00

No pictures to display

Door R L, Dent(s), Acceptable

0,00

No pictures to display

Trunk lid covering R, Scratch(es), Smart repair

110,64



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)

95,00



Mirror side blinker R, Scratch(es), Acceptable

0,00

No pictures to display

Rearview mirror R complete, Scratch(es), Acceptable

0,00

No pictures to display

Wing R R, Dent(s), Acceptable

0,00

No pictures to display

Door R R, Dent(s), Acceptable

0,00

No pictures to display

Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)

95,00

