



## FIAT DOBLO CARGO: LQ8995

Vinnumber:	<b>ZFA26300006B74511</b>	Versionname:	<b>1.6 MULTIJET 105 SX LWB</b>
First Registrationdate:	<b>22/01/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>116561</b>	Power Kw:	<b>77</b>
Bodytype:		Body color:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1311</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>2</b>		
Number head rests:	<b>2</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>No</b>		

## Options

GPS storage	<b>HD</b>	Central consol F
GPS storage		Rear parking sensors
Windows electric F		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Manual climate control</b>	

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

## Degree of wear

	<b>195/60/16/99 T Steel</b>			
Winter tyres:	Fr.L.	<b>Uniroyal: 4 mm</b>	Fr.R.	<b>Uniroyal: 4 mm</b>
	Re.L.	<b>Vredestein: 3 mm</b>	Re.R.	<b>Vredestein: 3 mm</b>

## Assistance equipment

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT	991,90
Door R R, Dent(s), PDR - Paintless dent repair	63,00



Foglight L, Scratch(es), Forfeit 115,00



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Mirror side blinker R, Broken, E - Replace 28,50



Windscreen, Stone chip(s), E - Replace 395,40



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Dent(s), Acceptable 0,00

No pictures to display

Mirror side blinker L, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover F L, Scratch(es), Acceptable 0,00

No pictures to display

Interior, Damaged, Acceptable 0,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 158,85



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 231,15



