



**MERCEDES C BERLINE: 1KRV362**

Vinnumber:	<b>WDD2050121F217804</b>	Versionname:	<b>2.1 C 300 BLUETEC HYBRID AMG LINE</b>
First Registrationdate:	<b>18/06/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>115164</b>	Power Kw:	<b>170</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Hybrid Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2721</b>
Number of doors:	<b>4</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Seats electric F L	
GPS storage		Seats electric F R	
GPS storage	<b>HD</b>	Sun Roof electric	
Windows electric F		Panoramic roof	
Windows electric R		Central consol F	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Seats F heated		Rear parking sensors	
Radio multimedia			
Type of headlighting	<b>Headlighting LED</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		
Head-up Display			

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>NOT OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>225/45/18/95 H LightMetal</b>				
Winter tyres:	Fr.L.	<b>Bridgestone: 3 mm</b>	Fr.R.	<b>Bridgestone: 3 mm</b>
	Re.L.	<b>Bridgestone: 3 mm</b>	Re.R.	<b>Bridgestone: 3 mm</b>

**Assistance equipment**

Repair kit	<b>No</b>	Compressor	<b>No</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

<b>Total cost ex VAT</b>	<b>1197,20</b>
<b>Tyre F R, Tear, E - Replace</b>	<b>153,60</b>



Alloy rim F L polished, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F L, Scratch(es), It - Spot repair 115,56



Alloy rim F R polished, Scratch(es), Acceptable 0,00

No pictures to display

Compressor, Missing, E - Replace 0,00



Wing R L, Dent(s), Acceptable 0,00

No pictures to display

Tyre repair kit, Missing, E - Replace 252,64



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper F R, Scratch(es), It - Spot repair 115,56



Wing R R, Scratch(es), LI - Repair and paint (complete) 369,84

