



FIAT DOBLO CARGO: LQ8993

Vinnumber:	ZFA26300006B74483	Versionname:	1.6 MULTIJET 105 SX LWB
First Registrationdate:	22/01/2016	Fiscalpower:	
Expertise Mileage:	102292	Power Kw:	77
Bodytype:		Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4816
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	2		
Number head rests:	2		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Central consol F
Steering wheel multifunctional	Rear parking sensors
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Winter tyres:	195/60/16/92 MS Steel			
	Fr.L.	Uniroyal: 4 mm	Fr.R.	Uniroyal: 4 mm
	Re.L.	Uniroyal: 5 mm	Re.R.	Uniroyal: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1324,69
-------------------	----------------

Bumper R, Scratch(es), LI - Repair and paint (complete)	158,85
---	---------------



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	231,15
---	---------------



Bonnet, Scratch(es), Acceptable 0,00

No pictures to display

Windscreen, Stone chip(s), Windscreen repair 58,80



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 238,76



Rearview mirror L complete, Broken, E - Replace 138,00



Roof, Dent(s), LI - Repair and paint (complete) 361,13



Rearview mirror R complete, Broken, E - Replace 138,00



Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Interior, Damaged, Acceptable 0,00

