



CITROEN GRAND C4 PICASSO: 1NAN404

Vinnumber:	VF73ABHXMJ890331	Versionname:	1.6 BLUEHDI 115 S/S MAN6 BUS. GPS & LTH.
First Registrationdate:	5/01/2016	Fiscalpower:	
Expertise Mileage:	171683	Power Kw:	85
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2402
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage		Seats electric F R	
GPS storage	HD	Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Rear parking sensors	
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/96 H LightMetal				
Winter tyres:	Fr.L.	Vredestein: 3 mm	Fr.R.	Vredestein: 3 mm
	Re.L.	Goodyear: 3 mm	Re.R.	Goodyear: 3 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT 2772,03

Windscreen, Stone chip(s), Acceptable 0,00



Roof, Dent(s), PDR - Paintless dent repair

82,80




Tailgate, Scratch(es), Acceptable

0,00

No pictures to display

Bonnet, Dent(s), PDR - Paintless dent repair

63,00



Wing R L, Dent(s), Acceptable

0,00

No pictures to display

Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim F R, Scratch(es), Acceptable

0,00



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)

115,56



Trunk lid covering R, Scratch(es), Smart repair

110,64



Door panel R L, Scratch(es), E - Replace

114,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Roof, Dent(s), Acceptable 0,00

No pictures to display

Wing R L, Dent(s), PDR - Paintless dent repair 63,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 308,20




Door R L, Scratch(es), Acceptable 0,00

No pictures to display


Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Door R R, Dent(s), LI - Repair and paint (complete) 318,35



Wing F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 316,18



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Mirror side blinker R, Crack, E - Replace

30,00

