



MERCEDES C BREAK: 1NUP959

Vinnumber:	WDD2052071F377647	Versionname:	2.1 C 200 D AVANTGARDE AUTO
First Registrationdate:	29/04/2016	Fiscalpower:	
Expertise Mileage:	200911	Power Kw:	100
Bodytype:		Body color:	Silver
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4111
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Sun Roof electric	
GPS storage	SD	Panoramic roof	
GPS storage		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	Tow bar removable
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Level control			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/50/17/98 WINTER V LightMetal				
Winter tyres:	Fr.L.	Uniroyal: 6 mm	Fr.R.	Uniroyal: 6 mm
	Re.L.	Uniroyal: 6 mm	Re.R.	Uniroyal: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1117,06
Roof, Scratch(es), LI - Repair and paint (complete)	481,50



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Wing R R, Scratch(es), LI - Repair and paint (complete)

308,20



Boot carpet, Damaged, Acceptable

0,00



Internal Boot Lining L, Hole, Acceptable

0,00



Alloy rim R R, Scratch(es), Acceptable

0,00

No pictures to display

Rocker panel inner F L, Dent(s), Acceptable

0,00

No pictures to display

Rearlight R , Scratch(es), 67 - Polish

0,00



Bumper F, Scratch(es), Acceptable

0,00

No pictures to display

Rocker panel inner R L, Scratch(es), Acceptable

0,00

No pictures to display

Tailgate, Scratch(es), It - Spot repair

115,56



Alloy rim F R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Trunk lid covering R, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Rocker panel inner R R, Scratch(es), Acceptable	0,00
---	------

No pictures to display