



MERCEDES C BREAK: 1JRU392

Vinnumber:	WDD2052361F160874	Versionname:	1.6 C 180 BLUETEC
First Registrationdate:	10/02/2015	Fiscalpower:	
Expertise Mileage:	91349	Power Kw:	85
Bodytype:	Break	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2729
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage	SD	Luggage cover
GPS storage		Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/92 H LightMetal				
Winter tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	847,36
Door F L, Scratch(es), Acceptable	0,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Rocker panel inner F R, Dent(s), LI - Repair and paint (complete)

115,56



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

211,80



Alloy rim F L, Scratch(es), Acceptable

0,00

No pictures to display

Rocker panel inner R L, Scratch(es), Acceptable

0,00

No pictures to display

Wing R L, Dent(s), LI - Repair and paint (complete)

308,20



Windscreen, Stone chip(s), Windscreen repair

0,00

