



**VOLVO XC60: 1NRX271**

Vinnumber:	<b>YV1DZARCDG2920350</b>	Versionname:	<b>2.0 D3 2WD GEARTRONIC SUMMUM</b>
First Registrationdate:	<b>12/04/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>136611</b>	Power Kw:	<b>110</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>4 Weel</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4831</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Seats electric F L	
GPS storage	<b>HD</b>	Seats electric F R	
GPS storage		Sun Roof electric	
Windows electric F		Panoramic roof	
Windows electric R		Central consol F	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Seats F heated		Rear parking sensors	
Radio multimedia		Type of Tow bar	<b>Tow bar fixed</b>
Type of headlighting	<b>Headlighting Xenon</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>NOT OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>


**Degree of wear**

<b>235/55/19/105 V LightMetal</b>				
Summer tyres:	Fr.L.	<b>Semperit: 3 mm</b>	Fr.R.	<b>Semperit: 3 mm</b>
	Re.L.	<b>Semperit: 3 mm</b>	Re.R.	<b>Semperit: 3 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

<b>Total cost ex VAT</b>	<b>469,89</b>
<b>Bonnet, Chemical polution, LI - Repair and paint (complete)</b>	<b>348,09</b>



Windscreen, Stone chip(s), Windscreen repair	58,80
--	-------



Door F R, Dent(s), Acceptable	0,00
-------------------------------	------

*No pictures to display*

Roof pillar L, Dent(s), Acceptable	0,00
------------------------------------	------

*No pictures to display*

Wing R R, Dent(s), PDR - Paintless dent repair	63,00
--	-------



Wing R R, Dent(s), Acceptable	0,00
-------------------------------	------

*No pictures to display*

Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*