



**PEUGEOT 308 SW: 1LUY370**

|                                    |                          |              |                                    |
|------------------------------------|--------------------------|--------------|------------------------------------|
| Vinnumber:                         | <b>VF3LCBHY8FS326109</b> | Versionname: | <b>1.6 BLUEHDI 73KW S/S ACTIVE</b> |
| First Registrationdate:            | <b>11/12/2015</b>        | Fiscalpower: |                                    |
| Expertise Mileage:                 | <b>104379</b>            | Power Kw:    | <b>73</b>                          |
| Bodytype:                          |                          | Body color:  | <b>Black</b>                       |
| Gearbox:                           | <b>MAN 5 VIT</b>         | Paint type:  | <b>Metalic</b>                     |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Aluminium</b>                   |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                          |
| Maintenance:                       | <b>OK</b>                | Parking lot: | <b>4206</b>                        |
| Battery functioning:               | <b>Yes</b>               |              |                                    |
| Number of doors:                   | <b>5</b>                 |              |                                    |
| Number of seats:                   | <b>5</b>                 |              |                                    |
| Number head rests:                 | <b>5</b>                 |              |                                    |
| Rims summer:                       | <b>Aluminium</b>         |              |                                    |
| Category:                          | <b>Passenger Car</b>     |              |                                    |
| Oil level:                         | <b>OK</b>                |              |                                    |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                                    |

**Options**

|                                |                              |
|--------------------------------|------------------------------|
| Windows electric F             | Central consol F             |
| Windows electric R             | Luggage cover                |
| Cruise Control                 | Rear parking sensors         |
| Steering wheel multifunctional |                              |
| Radio multimedia               |                              |
| Type of headlighting           | <b>Headlighting Halogen</b>  |
| Type of GPS                    | <b>GPS big screen color</b>  |
| Type of Lining                 | <b>Lining fabrics</b>        |
| Type of climate control        | <b>Autom climate control</b> |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**










|               |                                   |                       |       |                       |
|---------------|-----------------------------------|-----------------------|-------|-----------------------|
|               | <b>205/55/16/92 MS LightMetal</b> |                       |       |                       |
| Winter tyres: | Fr.L.                             | <b>Michelin: 4 mm</b> | Fr.R. | <b>Michelin: 4 mm</b> |
|               | Re.L.                             | <b>Michelin: 5 mm</b> | Re.R. | <b>Michelin: 5 mm</b> |

**Assistance equipment**

|                       |            |      |            |
|-----------------------|------------|------|------------|
| Emergency spare wheel | <b>Yes</b> | Jack | <b>Yes</b> |
|-----------------------|------------|------|------------|

|                                       |                |
|---------------------------------------|----------------|
| Total cost ex VAT                     | <b>2108,50</b> |
| Rear window, Scratch(es), E - Replace | <b>0,00</b>    |



|   |        |
|---|--------|
| Internal Boot Lining R, Broken, E - Replace   | 15,00  |
|     |        |
| Ignition key, Missing, E - Replace  | 0,00   |
| <i>No pictures to display</i>   |        |
| Roof, Chemical polution, LI - Repair and paint (complete)                           | 481,50 |
|    |        |
| Bumper F, Scratch(es), Acceptable   | 0,00   |
| <i>No pictures to display</i>   |        |
| Alloy rim F L, Scratch(es), LI - Repair and paint (complete)                        | 95,00  |
|    |        |
| Alloy rim R R, Scratch(es), LI - Repair and paint (complete)                        | 95,00  |
|   |        |
| Alloy rim R L, Scratch(es), LI - Repair and paint (complete)                        | 95,00  |
|  |        |
| Wing R R, Chemical polution, LI - Repair and paint (complete)                       | 308,20 |
|  |        |
| Bumper R, Scratch(es), LI - Repair and paint (complete)                             | 211,80 |
|  |        |
| Door F L, Scratch(es), Acceptable   | 0,00   |
| <i>No pictures to display</i>   |        |
| Alloy rim F R, Scratch(es), LI - Repair and paint (complete)                        | 95,00  |
|  |        |
|  |        |
| Door R R, Dent(s), Acceptable   | 0,00   |
| <i>No pictures to display</i>   |        |
| Wing R L, Dent(s), Acceptable   | 0,00   |
| <i>No pictures to display</i>   |        |
| Sill outer L, Dent(s) and scratch(es), Le - Replace and paint                       | 712,00 |

