



MERCEDES CLA SHOOTING BRAKE: 1KSH793

Vinnumber:	WDD1179081N233373	Versionname:	2.1 CLA 200 CDI URBAN SHOOTING BRAKE
First Registrationdate:	23/06/2015	Fiscalpower:	100
Expertise Mileage:	118046	Power Kw:	Grey
Bodytype:		Body color:	Metalic
Gearbox:	MAN 6 VIT	Paint type:	Aluminium
Transmission:	Front	Rims summer:	OK
Fueltype:	Diesel	Oil level:	1721
Maintenance:	OK	Parking lot:	
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	1		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	SD Front parking sensors
Windows electric F	Rear parking sensors
Windows electric R	Type of Tow bar
Cruise Control	No Tow bar
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining semi-artificial leather
Type of climate control	Manual climate control
Sport seats	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

25/45/17/91 W LightMetal				
Summer tyres:	Fr.L.	Yokohama: 3 mm	Fr.R.	Yokohama: 3 mm
	Re.L.	Yokohama: 4 mm	Re.R.	Yokohama: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	641,06
Sill outer R, Scratch(es), LI - Repair and paint (complete)	310,50



Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Bumper F R, Scratch(es), It - Spot repair 115,56



Seat cover F R, Stain, Cleaning 25,00



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00

