



**MERCEDES CLA: 1LNR657**

Vinnumber:	<b>WDD1173121N310535</b>	Versionname:	
First Registrationdate:	<b>29/10/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>91940</b>	Power Kw:	<b>80</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1122</b>
Number of doors:	<b>4</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Panoramic roof	
GPS storage		Central consol F	
GPS storage	<b>SD</b>	Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/55/16/91 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Uniroyal: 4 mm</b>	Re.R.	<b>Uniroyal: 4 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

<b>Total cost ex VAT</b>	<b>2240,06</b>
--------------------------	----------------

<b>Door R L, Scratch(es), Acceptable</b>	<b>0,00</b>
--	-------------

*No pictures to display*

<b>Door F R, Dent(s), Acceptable</b>	<b>0,00</b>
--------------------------------------	-------------

No pictures to display

Bumper R, Dent(s), LI - Repair and paint (complete)	211,80
---	--------



Rocker panel inner R R, Dent(s), LI - Repair and paint (complete)	115,56
---	--------



Roof, Chemical pollution, LI - Repair and paint (complete)	481,50
--	--------



Door R L, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Door panel R L, Scratch(es), E - Replace	114,00
--	--------



Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Windscreen, Stone chip(s), E - Replace	487,20
--	--------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Bumper F, Crack, Le - Replace and paint	735,00
---	--------



Tailgate, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Rearview mirror housing L, Scratch(es), Acceptable	0,00
--	------

No pictures to display