


**NISSAN QASHQAI: 1JKX451**

Vinnnumber:	<b>SJNFDAJ11U1051161</b>	Versionname:	<b>1.6 DCI ACENTA</b>
First Registrationdate:	<b>13/01/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>158831</b>	Power Kw:	<b>96</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1210</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	<b>Tow bar removable</b>
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>No GPS</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>215/60/17/100 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Michelin: 8 mm</b>	Fr.R.	<b>Michelin: 8 mm</b>
	Re.L.	<b>Michelin: 7 mm</b>	Re.R.	<b>Michelin: 7 mm</b>

**Assistance equipment**

Repair kit	<b>No</b>	Compressor	<b>Yes</b>
------------	-----------	------------	------------

Total cost ex VAT 931,32

Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 510,35





Bumper R, Scratch(es), Acceptable 0,00



Dashboard, Tear, Acceptable 0,00



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 0,00



Tyre repair kit, Missing, E - Replace 0,00



Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 268,18



Wheel arch cover F R, Scratch(es), E - Replace 152,79



Wing R R, Scratch(es), LI - Repair and paint (complete) 0,00



Wheel arch cover R R, Broken, E - Replace 0,00

