


**RENAULT MEGANE GRANDTOUR: 1LRD295**

Vinnumber:	<b>VF1KZ0C0H53978963</b>	Versionname:	<b>1.5 DCI 95 TOMTOM? EDITION</b>
First Registrationdate:	<b>13/11/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>179968</b>	Power Kw:	<b>70</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>NOT OK</b>	Parking lot:	<b>3415</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/55/16/92 MS Steel</b>			
Winter tyres:	Fr.L.	<b>Pirelli: 4 mm</b>	Fr.R.	<b>Pirelli: 4 mm</b>
	Re.L.	<b>Pirelli: 5 mm</b>	Re.R.	<b>Pirelli: 5 mm</b>

**Assistance equipment**

Spare wheel	<b>No</b>	Jack	<b>Yes</b>
Total cost ex VAT			<b>1199,74</b>
Wing F R, Scratch(es), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete)			<b>310,50</b>



Wheel cover R L, Scratch(es), Acceptable 0,00

*No pictures to display*

Rear window, Scratch(es), E - Replace 370,00



Spare wheel, Missing, E - Replace 196,80



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Maintenance, Maintenance, Execute 0,00

*No pictures to display*

Door moulding Lower R R, Scratch(es), Smart repair 110,64

