



**LU Volkswagen Sharan: XH6085**

|                                    |                          |              |                                      |
|------------------------------------|--------------------------|--------------|--------------------------------------|
| Vinnumber:                         | <b>WVWZZZ7NZFV051163</b> | Versionname: | <b>2.0 TDI CR 103KW HIGHLINE BMT</b> |
| First Registrationdate:            | <b>3/07/2015</b>         | Fiscalpower: |                                      |
| Expertise Mileage:                 | <b>145803</b>            | Power Kw:    | <b>103</b>                           |
| Bodytype:                          |                          | Body color:  | <b>Silver</b>                        |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metallic</b>                      |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Aluminium</b>                     |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                            |
| Maintenance:                       | <b>OK</b>                | Parking lot: | <b>2302</b>                          |
| Battery functioning:               | <b>Yes</b>               |              |                                      |
| Number of doors:                   | <b>5</b>                 |              |                                      |
| Number of seats:                   | <b>7</b>                 |              |                                      |
| Number head rests:                 | <b>7</b>                 |              |                                      |
| Rims summer:                       | <b>Aluminium</b>         |              |                                      |
| Category:                          | <b>Passenger Car</b>     |              |                                      |
| Oil level:                         | <b>OK</b>                |              |                                      |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                                      |

**Options**

|                                |                              |
|--------------------------------|------------------------------|
| Radio CD                       | Sun Roof electric            |
| Windows electric F             | Panoramic roof               |
| Windows electric R             | Central consol F             |
| Cruise Control                 | Luggage cover                |
| Steering wheel multifunctional | Front parking sensors        |
| Seats F heated                 | Rear parking sensors         |
| Type of headlighting           | <b>Headlighting Xenon</b>    |
| Type of GPS                    | <b>GPS big screen color</b>  |
| Type of Lining                 | <b>Lining leather</b>        |
| Type of climate control        | <b>Autom climate control</b> |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|                                   |       |                       |       |                       |
|-----------------------------------|-------|-----------------------|-------|-----------------------|
| <b>225/50/17/92 MS LightMetal</b> |       |                       |       |                       |
| Winter tyres:                     | Fr.L. | <b>Michelin: 5 mm</b> | Fr.R. | <b>Michelin: 5 mm</b> |
|                                   | Re.L. | <b>Michelin: 6 mm</b> | Re.R. | <b>Michelin: 6 mm</b> |

**Assistance equipment**

|  |         |
|--|---------|
| Total cost ex VAT                              | 1100,66 |
| Door F L, Dent(s), Acceptable                  | 0,00    |
| <i>No pictures to display</i>                  |         |
| Wing R R, Dent(s), PDR - Paintless dent repair | 63,00   |



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 382,02



Windscreen, Stone chip(s), E - Replace 560,64



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Rearview mirror housing R, Scratch(es), Acceptable 0,00

*No pictures to display*

Bumper R, Scratch(es), Acceptable 0,00

*No pictures to display*

Interior, Dirty, Cleaning 0,00

*No pictures to display*