



**RENAULT Grand Scenic: 1HYT676**

|                                    |                          |              |                  |
|------------------------------------|--------------------------|--------------|------------------|
| Vinnnummer:                        | <b>VF1JZNAB651735972</b> | Versionname: | <b>DCI</b>       |
| First Registrationdate:            | <b>31/10/2014</b>        | Fiscalpower: |                  |
| Expertise Mileage:                 | <b>101691</b>            | Power Kw:    | <b>96</b>        |
| Bodytype:                          |                          | Body color:  | <b>Blue</b>      |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>   |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Aluminium</b> |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>        |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>1427</b>      |
| Number of doors:                   | <b>5</b>                 |              |                  |
| Number of seats:                   | <b>7</b>                 |              |                  |
| Number head rests:                 | <b>7</b>                 |              |                  |
| Rims summer:                       | <b>Aluminium</b>         |              |                  |
| Category:                          | <b>Passenger Car</b>     |              |                  |
| Oil level:                         | <b>OK</b>                |              |                  |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                  |

**Options**

|                                |                                       |                       |
|--------------------------------|---------------------------------------|-----------------------|
| Radio CD                       |                                       | Sun Roof electric     |
| GPS storage                    |                                       | Panoramic roof        |
| GPS storage                    | <b>SD</b>                             | Central consol F      |
| Windows electric F             |                                       | Luggage cover         |
| Windows electric R             |                                       | Front parking sensors |
| Cruise Control                 |                                       | Rear parking sensors  |
| Steering wheel multifunctional |                                       |                       |
| Radio multimedia               |                                       |                       |
| Type of headlighting           | <b>Headlighting Halogen</b>           |                       |
| Type of GPS                    | <b>GPS big screen color</b>           |                       |
| Type of Lining                 | <b>Lining semi-artificial leather</b> |                       |
| Type of climate control        | <b>Autom climate control</b>          |                       |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                  |                         |       |                         |
|---------------|----------------------------------|-------------------------|-------|-------------------------|
|               | <b>205/55/17/95 V LightMetal</b> |                         |       |                         |
| Winter tyres: | Fr.L.                            | <b>Vredestein: 6 mm</b> | Fr.R. | <b>Vredestein: 6 mm</b> |
|               | Re.L.                            | <b>Michelin: 6 mm</b>   | Re.R. | <b>Michelin: 6 mm</b>   |

**Assistance equipment**

|            |            |            |            |
|------------|------------|------------|------------|
| Repair kit | <b>Yes</b> | Compressor | <b>Yes</b> |
|------------|------------|------------|------------|

|  |               |
|--|---------------|
| Total cost ex VAT  | <b>520,80</b> |
| Alloy rim F R, Scratch(es), LI - Repair and paint (complete) | <b>95,00</b>  |



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

235,80



Bumper F, Scratch(es), Acceptable

0,00

*No pictures to display*

Door F L, Scratch(es), Acceptable

0,00

*No pictures to display*

Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim R R, Scratch(es), Acceptable

0,00

*No pictures to display*

Seat cover R L, Stain, Acceptable

0,00

*No pictures to display*

Rearview mirror housing R, Scratch(es), Acceptable

0,00

*No pictures to display*

Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Wheel aperture R R, Dent(s) and scratch(es), Acceptable

0,00

*No pictures to display*