


SKODA OCTAVIA COMBI: 1NFJ631

Vinnumber:	TMBJG7NE5G0182527	Versionname:	1.6 CRTDI 81KW DSG 7 GREENTEC AMBITION
First Registrationdate:	11/02/2016	Fiscalpower:	
Expertise Mileage:	145172	Power Kw:	81
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2615
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage		Central consol F	
GPS storage	SD	Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------


Total cost ex VAT	776,13
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00



Trunk lid covering R, Scratch(es), Acceptable 0,00

No pictures to display

Roof, Dent(s), PDR - Paintless dent repair 82,80



Door R R, Scratch(es), LI - Repair and paint (complete) 318,35



Reflector, Broken, E - Replace 11,80



Bumper R, Dent(s) and scratch(es), Le - Replace and paint 0,00



Bumper F, Crack, Le - Replace and paint 0,00





Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

268,18



Windscreen, Crack, E - Replace

0,00

