


SKODA OCTAVIA COMBI: 1LHC884

Vinnumber:	TMBJG7NE2G0082434	Versionname:	1.6 CRTDI 81KW GREENTEC AMBITION
First Registrationdate:	28/09/2015	Fiscalpower:	
Expertise Mileage:	142120	Power Kw:	81
Bodytype:		Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3804
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Seats F heated	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining semi-artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/92 H LightMetal				
Summer tyres:	Fr.L.	Fulda: 5 mm	Fr.R.	Fulda: 5 mm
	Re.L.	Fulda: 6 mm	Re.R.	Fulda: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			796,80
Reflector, Broken, E - Replace			23,60



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	308,20
---	--------



Rear window, Scratch(es), E - Replace	370,00
---------------------------------------	--------

