



**SKODA FABIA COMBI: 1KSE870**

Vinnumber:	<b>TMBJJ6NJ6GZ017512</b>	Versionname:	<b>1.4 CRTDI 66KW AMBITION</b>
First Registrationdate:	<b>22/06/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>180525</b>	Power Kw:	<b>66</b>
Bodytype:		Body color:	<b>White</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>SERVICE IN 1500KM</b>		
Maintenance:	<b>OK</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>4</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Windows electric F	Central consol F
Cruise Control	Luggage cover
Radio multimedia	Rear parking sensors
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>No GPS</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Manual climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>195/60/15/84 H Steel</b>				
Summer tyres:	Fr.L.	<b>Hankook: 6 mm</b>	Fr.R.	<b>Hankook: 4 mm</b>
	Re.L.	<b>Kumho: 5 mm</b>	Re.R.	<b>Kumho: 5 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	1358,56
Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	374,68



Roof, Dent(s), Acceptable

No pictures to display

Bodywork, Not original part, Remove lettering

0,00



Wheel cover R R, Scratch(es), E - Replace

24,00



Seat cover F L, Dirty, Cleaning

25,00



Bumper F, Broken, Le - Replace and paint

607,20



Wheel cover F L, Scratch(es), E - Replace

24,00



Wing R R, Dent(s), Acceptable

0,00

No pictures to display

Door F L, Scratch(es), LI - Repair and paint (complete)

254,68



Wheel cover F R, Scratch(es), E - Replace

24,00



Wheel cover R L, Scratch(es), Acceptable

0,00

No pictures to display

Seat cover F R, Dirty, Cleaning

25,00

