



SKODA OCTAVIA: 1NEB675

Vinnumber:	TMBAG9NE2G0173148	Versionname:	1.6 CRTDI 81KW DSG 7 GREENTEC STYLE
First Registrationdate:	2/02/2016	Fiscalpower:	
Expertise Mileage:	113699	Power Kw:	81
Bodytype:		Body color:	Brown
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	18 DAGEN	Parking lot:	3730
Maintenance:	3800		
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage	HD	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Seats F heated			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Continental: 6 mm	Fr.R.	Continental: 6 mm
	Re.L.	Continental: 8 mm	Re.R.	Continental: 8 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Total cost ex VAT			32,40
Bumper R, Repaired, Acceptable			0,00
<i>No pictures to display</i>			
Door R R, Dent(s) and scratch(es), Acceptable			0,00

<i>No pictures to display</i>		
Door F R, Dent(s), Acceptable		0,00
<i>No pictures to display</i>		
Bumper grille, Broken, E - Replace		32,40
Rear bulkhead lining, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Alloy rim R R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
License plate F, Deformed / Strained, E - Replace		0,00
Door F L, Dent(s) and scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Tires, Not original part, Acceptable		0,00
<i>No pictures to display</i>		
Gear shift lever knob, Worn, Acceptable		0,00
<i>No pictures to display</i>		
Tailgate, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Roof, Dent(s), Acceptable		0,00
<i>No pictures to display</i>		
Windscreen, Bad repair, Acceptable		0,00
<i>No pictures to display</i>		
Seat F L compl, Worn, Acceptable		0,00
<i>No pictures to display</i>		
Bumper F, Stone chip(s), Acceptable		0,00
<i>No pictures to display</i>		