



RENAULT MEGANE GRANDTOUR: 1LLR364

Vinnumber:	VF1KZ890H54003055	Versionname:	1.5 ENERGY DCI 110 BOSE ? EDITION
First Registrationdate:	21/10/2015	Fiscalpower:	
Expertise Mileage:	73741	Power Kw:	81
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1214
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	No		

Options

Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/50/17/93 H LightMetal				
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	2147,21
--------------------------	----------------

Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)	318,35
--	---------------



Registration Document, Missing, E - Replace 150,00



Wing F L, Dent(s) and scratch(es), Le - Replace and paint 530,02



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 308,20



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper corner R L, Scratch(es), It - Spot repair 115,56



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Door R R, Dent(s), Acceptable 0,00

No pictures to display

Bonnet, Dent(s) and scratch(es), LI - Repair and paint (complete) 290,08



Certificate Of Conformity, Missing, E - Replace 150,00



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper spoiler F, Scratch(es), Acceptable 0,00

No pictures to display

