



VOLVO XC60: 1PGC849

Vinnumber:	VV1DZARC1H2025558	Versionname:	2.0 D3 2WD KINETIC
First Registrationdate:	28/06/2016	Fiscalpower:	
Expertise Mileage:	104429	Power Kw:	110
Bodytype:		Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4607
Maintenance:	SERVICE 4333KM 1M		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage	HD	Luggage cover
GPS storage		Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

235/65/17/108 V LightMetal				
Summer tyres:	Fr.L.	N.D.	Fr.R.	N.D.
	Re.L.	Pirelli: 4 mm	Re.R.	Pirelli: 4 mm
235/65/17/108 V LightMetal				
Winter tyres:	Fr.L.	Goodyear: 7 mm	Fr.R.	Goodyear: 7 mm
	Re.L.	N.D.	Re.R.	N.D.

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			56,80
Seat cover F R, Stain, Cleaning			25,00



Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bumper Trim F, Missing, E - Replace	31,80
-------------------------------------	-------



Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display