



VOLKSWAGEN Passat: 1GKN194

Vinnnummer:	VWZZZ3CZEE085880	Versionname:	PASSAT BER Comfortline BMT 105PK
First Registrationdate:	4/03/2014	Fiscalpower:	
Expertise Mileage:	126557	Power Kw:	77
Bodytype:		Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	1412
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Front parking sensors
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/55/16/92 H LightMetal				
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Total cost ex VAT			2383,17
Bonnet, Chemical polution, LI - Repair and paint (complete)			290,08



Wing F L, Scratch(es), Acceptable 0,00

No pictures to display


Headlight L, Scratch(es), E - Replace 396,00



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Bumper R, Scratch(es), LI - Repair and paint (complete) 235,80



Tailgate, Chemical pollution, LI - Repair and paint (complete) 301,68




Tailgate, Chemical pollution, LI - Repair and paint (complete) 301,68



Tailgate, Chemical pollution, LI - Repair and paint (complete) 301,68



Roof, Chemical pollution, LI - Repair and paint (complete) 481,56



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete) 115,56



Rearview mirror housing L, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Scratch(es), LI - Repair and paint (complete) 318,35



Door R R, Scratch(es), LI - Repair and paint (complete) 318,35

