



VOLKSWAGEN GOLF VII: BN5275

Vinnumber:	WVWZZZAUZGP010469	Versionname:	1.6 TDI 81KW TRENDLINE
First Registrationdate:	26/01/2016	Fiscalpower:	
Expertise Mileage:	159858	Power Kw:	81
Bodytype:		Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2327
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	SD	Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/92 H Steel			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	2264,91
-------------------	----------------

Wing F L, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Rear window, Scratch(es), E - Replace	370,00
---------------------------------------	---------------



Bumper F, Crack, Le - Replace and paint 735,00



Door F L, Scratch(es), It - Spot repair 115,56



Rearview mirror housing L, Scratch(es), Acceptable 0,00

No pictures to display

Reflector, Broken, E - Replace 27,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Windscreen, Stone chip(s), E - Replace 487,20



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Rust, LI - Repair and paint (complete) 318,35



Wheel cover R R, Scratch(es), Acceptable 0,00

No pictures to display

Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

