



**TOYOTA Aygo: 1CET985**

Vinnumber:	JTDJG12C60N585747	Versionname:	AYGO BER 68PK
First Registrationdate:	7/11/2011	Fiscalpower:	
Expertise Mileage:	35743	Power Kw:	50
Bodytype:		Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Petrol	Oil level:	OK
Maintenance:	OK	Parking lot:	4128
Battery functioning:	Yes		
Number of doors:	3		
Number of seats:	4		
Number head rests:	2		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

**Options**

Radio CD	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics

**Limited Technical Inspection**

Tires wear profile	OK	Battery functioning	Yes
Idle position	OK	Power steering	Yes
Engine startingtime	OK	Sound engine	OK
Exhaust gass	OK	Clutch test	OK
Handbrake	OK	Wiper fluid level	OK
		Transmission	OK
		Lighting	OK
		Wiperblades	OK

**Degree of wear**

<b>155/65/14/75 T Steel</b>				
Summer tyres:	Fr.L.	Continental: 3 mm	Fr.R.	Continental: 3 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

**Assistance equipment**

Emergency spare wheel	Yes	Jack	Yes
-----------------------	-----	------	-----

Total cost ex VAT	1073,12
-------------------	---------

Wheel cover R L, Scratch(es), E - Replace	24,00
---	-------



Steel rim F R, Deformed / Strained, E - Replace	75,84
---	-------



Wheel cover R R, Scratch(es), E - Replace

24,00



Wing R L, Rust, LI - Repair and paint (complete)

246,56



Wheel cover F L, Missing, E - Replace

24,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

169,44



Bumper F, Scratch(es), LI - Repair and paint (complete)

169,44



Floor covering F L, Tear, E - Replace

240,00



Steel rim F L, Deformed / Strained, E - Replace

75,84



Wheel cover F R, Missing, E - Replace

24,00



Door F L, Dent(s), Acceptable

0,00

No pictures to display

Rearview mirror housing R, Scratch(es), Acceptable

0,00

No pictures to display