



SKODA OCTAVIA: 1LDA048

Vinnumber:	TMBAG7NE9G0045400	Versionname:	1.6 CRTDI 81KW GREENTEC AMBITION
First Registrationdate:	25/08/2015	Fiscalpower:	
Expertise Mileage:	148959	Power Kw:	81
Bodytype:		Body color:	Blue
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4514
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage		Central consol F
GPS storage	SD	Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 V LightMetal				
Summer tyres:	Fr.L.	Michelin: 2 mm	Fr.R.	Michelin: 2 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm

Assistance equipment

Repair kit	Yes	Compressor	No
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	275,00
Windscreen, Stone chip(s), Windscreen repair	0,00



Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door R L, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Bumper F, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Ignition key, Missing, E - Replace	150,00
------------------------------------	--------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Tailgate, Bad repair, Acceptable	0,00
----------------------------------	------

No pictures to display

Compressor, Missing, E - Replace	125,00
----------------------------------	--------



Door F L, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display