



RENAULT CLIO GRANDTOUR: 1LFH029

Vinnumber:	VF17RFL0H53740350	Versionname:	1.5 ENERGY DCI 90 DYNAMIQUE
First Registrationdate:	14/09/2015	Fiscalpower:	
Expertise Mileage:	134471	Power Kw:	66
Bodytype:		Body color:	Silver
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4123
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear













	195/55/16/92 H LightMetal			
Summer tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1402,32
Bumper F, Scratch(es), LI - Repair and paint (complete)	169,44



Alloy rim F L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)		95,00
		
Bumper R, Scratch(es), It - Spot repair		115,56
		
Tailgate, Scratch(es), It - Spot repair		115,56
		
Rearlight R , Broken, E - Replace		96,00
		
Rear window, Scratch(es), E - Replace		320,00
		
Windscreen, Crack, E - Replace		413,76
		
Rearlight R tailgate, Broken, E - Replace		77,00
