



**VOLVO XC90: 1NGB018**

Vinnumber:	<b>VV1LFBABDG1066547</b>	Versionname:	<b>2.0 T8 4WD GEARTRONIC MOMENTUM 7PL.</b>
First Registrationdate:	<b>16/02/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>180032</b>	Power Kw:	<b>235</b>
Bodytype:		Body color:	<b>Brown</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>4 Weel</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Hybrid Petrol</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2504</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>7</b>		
Number head rests:	<b>7</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

GPS storage	<b>HD</b>	Seats R heated
GPS storage		Seats electric F L
Windows electric F		Seats electric F R
Windows electric R		Sun Roof electric
Cruise Control		Panoramic roof
Steering wheel multifunctional		Central consol F
Seats F heated		Luggage cover
Radio multimedia		Front parking sensors
Type of headlighting	<b>Headlighting LED</b>	Rear parking sensors
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining leather</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>NOT OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

Winter tyres:	<b>235/55/19/105 V LightMetal</b>			
	Fr.L.	<b>Bridgestone: 4 mm</b>	Fr.R.	<b>Bridgestone: 4 mm</b>
	Re.L.	<b>Bridgestone: 4 mm</b>	Re.R.	<b>Bridgestone: 4 mm</b>

**Assistance equipment**

Number of charging cables (normal)	<b>1</b>	Runflat	<b>Yes</b>
Number of charging cables (rapid charge)	<b>0</b>		

<b>Total cost ex VAT</b>	<b>1312,38</b>
<b>Bumper R, Scratch(es), LI - Repair and paint (complete)</b>	<b>254,16</b>



Bumper F R, Scratch(es), It - Spot repair 115,56



Windscreen, Stone chip(s), E - Replace 560,64



Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 382,02



Sill outer R, Scratch(es), Acceptable 0,00

No pictures to display