



SKODA FABIA COMBI: 1KNV348

Vinnumber:	TMBJJ6NJ3FZ070845	Versionname:	1.4 CRTDI 66KW AMBITION
First Registrationdate:	4/06/2015	Fiscalpower:	
Expertise Mileage:	123802	Power Kw:	66
Bodytype:		Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance	NU UITVOEREN	Parking lot:	2404
Maintenance	NOT OK		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Windows electric F	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Rear parking sensors
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/60/15/88 T Steel			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT 746,28

Bonnet, Dent(s), PDR - Paintless dent repair 63,00





Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover F R, Scratch(es), E - Replace 24,00



Wheel cover R L, Scratch(es), E - Replace 24,00



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Sill outer L, Dent(s) and scratch(es), LI - Repair and paint (complete) 296,40



Maintenance, Maintenance, Execute 0,00



Bumper R, Bad repair, LI - Repair and paint (complete) 169,44



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete) 169,44

