



VOLKSWAGEN POLO: 1JJG047

Vinnnumber:	WVWZZZ6RZFY044392	Versionname:	1.4 TDI 55KW TRENDLINE
First Registrationdate:	2/01/2015	Fiscalpower:	
Expertise Mileage:	52596	Power Kw:	55
Bodytype:		Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4121
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

175/70/14/92 H Steel				
Summer tyres:	Fr.L.	Uniroyal: 4 mm	Fr.R.	Uniroyal: 4 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	653,06
-------------------	--------

Wing R L, Dent(s), LI - Repair and paint (complete)	246,56
---	--------



Bonnet, Scratch(es), LI - Repair and paint (complete)	232,06
---	--------



Bumper R, Scratch(es), LI - Repair and paint (complete) 169,44



Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Rear wiper blade, Incomplete, E - Replace 5,00



Interior, Dirty, Cleaning 0,00



Wing R R, Dent(s), Acceptable 0,00

No pictures to display