


RENAULT ESPACE: 1KXY847

Vinnumber:	VF1RFC00153461252	Versionname:	1.6 DCI 160 EDC ENERGY INTENS
First Registrationdate:	29/07/2015	Fiscalpower:	
Expertise Mileage:	110528	Power Kw:	118
Bodytype:		Body color:	Gold
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2808
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage		Panoramic roof	
GPS storage	HD	Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Radio multimedia			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	235/60/18/107 H LightMetal			
Winter tyres:	Fr.L.	Dunlop: 6 mm	Fr.R.	Dunlop: 6 mm
	Re.L.	Dunlop: 7 mm	Re.R.	Dunlop: 7 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	356,16
Seat cover F L, Worn, Acceptable	0,00
<i>No pictures to display</i>	
Door frame R R, Dent(s), It - Spot repair	129,96



Bumper spoiler F, Scratch(es), Acceptable 0,00

No pictures to display

Door panel F L, Hole, Smart repair 110,64



Door frame R L, Dent(s), It - Spot repair 115,56



Wing R L, Dent(s), Acceptable 0,00

No pictures to display

Door frame F L, Dent(s), Acceptable 0,00

No pictures to display

Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper corner R R, Scratch(es), Acceptable 0,00

No pictures to display