



VOLKSWAGEN Passat: 1JEY644

Vinnumber:	WVWZZZ3CZFE074109	Versionname:	PASSAT VAR Comfortline 136PK
First Registrationdate:	28/11/2014	Fiscalpower:	
Expertise Mileage:	152645	Power Kw:	100
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2726
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Winter tyres:	215/55/16/97 H LightMetal			
	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	842,80
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80



Rearview mirror housing L, Scratch(es), Acceptable	0,00
----------------------------------------------------	------

No pictures to display

Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	356,20
---------------------------------------------------------------------	--------



Alloy rim F L polished, Scratch(es), Acceptable	0,00
-------------------------------------------------	------

No pictures to display

Rearview mirror housing R, Scratch(es), Acceptable	0,00
----------------------------------------------------	------

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80
---------------------------------------------------------	--------



Bonnet, Dent(s), Acceptable	0,00
-----------------------------	------

No pictures to display

Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bonnet, Dent(s), PDR - Paintless dent repair	63,00
----------------------------------------------	-------

